



VNT6656 Software

REVISION HISTORY

Revision 1.1
October 13, 2006

VIA TECHNOLOGIES, INC.

Copyright Notice:

Copyright © 2006, VIA Technologies, Incorporated. All Rights Reserved.

No part of this document may be reproduced, transmitted, transcribed, stored in a retrieval system, or translated into any language, in any form or by any means, electronic, mechanical, magnetic, optical, chemical, manual or otherwise without the prior written permission of VIA Technologies, Incorporated.

VNT6656GEV00 may only be used to identify WLAN products of VIA Technologies, Inc.



is a registered trademark of VIA Technologies, Incorporated.

All trademarks are the properties of their respective owners.

Disclaimer Notice:

No license is granted, implied or otherwise, under any patent or patent rights of VIA Technologies Inc. VIA Technologies Inc. makes no warranties, implied or otherwise, in regard to this document and to the products described in this document. The information provided by this document is believed to be accurate and reliable as of the publication date of this document. However, VIA Technologies Inc. assumes no responsibility for any errors in this document. Furthermore, VIA Technologies Inc. assumes no responsibility for the use or misuse of the information in this document and for any patent infringements that may arise from the use of this document. The information and product specifications within this document are subject to change at any time, without notice and without obligation to notify any person of such change.

Offices:

USA Office:

940 Mission Court
Fremont, CA 94539
USA
Tel: (510) 683-3300
Fax: (510) 683-3301 or (510) 687-4654
Web: www.vntek.com

Taipei Office:

8th Floor, No. 533
Chung-Cheng Road, Hsin-Tien
Taipei, Taiwan ROC
Tel: (886-2) 2218-2078
Fax: (886-2) 2219-8461
Web: www.vntek.com.tw

Revision History

Release	Date	Revision	Initials
1.0	2006-10-09	Initial release.	RTW
1.1	2006-10-13	To add the release version information	RTW

Table of Contents

1.	Driver Type and Root Information.....	1
1.1.	Driver.....	1
1.2.	Application Utility.....	1
2.	Driver Revision History	2
2.1.	Windows driver revision (v1.40)	2
2.2.	Linux driver revision (v1.12)	3

1. Driver Type and Root Information

1.1. Driver

Name	Ver.	Supporting OSes	Location	Note
NDIS5 for x86	1.40	Win98SE, WinME, Win2000, WinXP, Windows Server 2003	Root directory	
		Windows XP embedded SP1	\XPe\	
		Windows CE 4.0/4.2	\CE4\	
		Windows CE 5.0	\CE5\	
NDIS5 for AMD64	1.40	Windows XP, Windows Server 2003 for AMD64	Root directory	
Linux	1.12	Fedora Core 1 (x86, UP/SMP, 2.4.22-1.2115), Fedora Core 2 (x86, UP/SMP, 2.6.5-1.358), Fedora Core 3 (x86, UP/SMP, 2.6.9-1.667), Fedora Core 4 (x86, UP/SMP, 2.6.11-1.1369)	\LINUX\	

1.2. Application Utility

Name	Ver.	Supporting OSes	Location	Note
Winsetup	3.20	Win95, Win95OSR2, Win98, Win98SE, NT3.51, NT4.0, WinME, Win2000, WinXP, Windows Server 2003, WinXP 64bit Edition, Server 2003 64bit Edition	\WINSETUP\	
WifiSet	1.47	Win98SE, WinME, Win2000, WinXP, Windows Server 2003	\WifiSet\	
WifiSetCE	1.03	Windows CE 4.2/5.0	\WifiSetCE\	

PS: WHQL submission number of the Windows NDISWDM driver (v1.40) for x86/x64 is 1212105 in this software package.

2. Driver Revision History

2.1. Windows driver revision (v1.40)

1. Add Fake SSID from WZC handling
2. Fix the share authentication bugFix Data Alignment issue.
3. Fix x64 WHQL testing fail, bScheduleCommand fail and can't do scanning.
4. Patch the radio on/off for WZC and connect to AP in 6 seconds.
5. Release 1.32.146_migration_mode, for the Cisco migration mode issue.
6. Release 1.33.147_rdp, improve WinCE RDP w/ Winbench99 testing performance.
7. Add the EEP_LED_ACTSET for PCIE-mini card USB LED pin will be pulled high.
8. Turn LED off when the radio is off by hot key or wifiset. Back to slow_led when radio is back.
9. Fix LED initial state.
10. Check and set the LED priority and Radio control setting for Radio button.
11. Add the LED On for 3 seconds when Radio button is on.
12. Use GPIO0 output to enable / disable LED output.
13. Fix bug: Adhoc mode will cause reboot.
14. Fix bug: S/W AP mode will cause Wifiset terminated. or reboot.
15. Fix association with Cisco AP mixed mode issue; modify the cipher match algorithm for avoiding incorrect judgment.
16. Fix TKIP TSC replay warnings in Cisco AP.
17. Fix TKIP MIC Fails in Cisco AP.



2.2. Linux driver revision (v1.12)

1. Fixed adhoc mode can't be unregister/removed.
2. Source code support 2.4.x (RH9.0/2.4.10-8).
3. Fix bugs: 'ifconfig' can't open/down the device.
4. Patch for 'iwconfig', set wep key after ethX open.
5. Fix WEP share mode bugs.
6. Support hidden SSID function.
7. Fix adhoc rate fallback under 11M issue.
8. Add Migration mode patch.
9. Support WE-17 & wpa_supplicant-0.4.9(pre-test verion).
10. Fix remove driver issue while run with wpa_supplicant-0.4.9.
11. Fix 2.6.x SMP kernel crash issue (run with iperf).